## 05-44481-rdd Doc 11484-3 Filed 12/17/07 Entered 12/17/07 18:10:45 Exhibit Exhibit 1 to Affidavit of Harold Zaima - Copy and Supporting Documentati Pg 1 of 6

## KenSa, L.L.C.

36199 Mound Road Sterling Heights, MI 48310 Phone (586) 983-4270 Fax (586) 983-3531

Please Remit To: Department #268401 KenSa, LLC PO BOX 67000 **DETROIT MI 48267-2684** 

M39123	1/2//06
ORDER NO.	

INVOICE

BILL TO: DELPACKARD

PO BOX 431 408 DANA SIREE! ALIN: ACCOUNTS PAYABLE DEPT. M/S 91L

SHIP TO:

MATERIAL CLAIM

WARREN, OH 44486

United States

**United States** 

**PURCHASE ORDER/FOB** 

TERMS/SHIP VIA

**DUE DATE/FREIGHT** 

2/2//06


SEE BELOW

NET 30

Collect

			Collect	
LINE/ REL.	ITEM NO JDESC. SERIAL NO.	UNIT PRICE/ QTY. ORDERED	OTY. INVOICED DATE SHIPPED	EXTENDED PRICE
1	4 JR PARTS CANCELLED SEE ATTACHED	1 29,957.7300	29,957.7300	\$29,957.73
2	05087271AA SEE AITACHED	1 3613.59	3,613.5900	\$3,613.59
3	5059132 SEE ATTACHED	1 191.0000	191.0000	\$191.00
4	VALIDATION COSTS	1 23530	23,530.0000	\$23,530.00
5	ASSEMBLY CELLS	1 2945.77	2,945.7700	\$2,945.77
The state of the s				
			·	
			Sale Amount Total Amount \$	\$60,238.09 \$60,238.09
				Jone 1

05-44481-rdd Doc 11484-3 Filed 12/17/07 Entered 12/17/07 18:10:45 Exhibit 1 to Affidavit of Harold Zaima - Copy and Supporting Documentati Pg 2 of 6



36199 Mound Rd. Sterling Heights, MI 48310 Phone 586-983-4270 Fax 586-983-3531

# **CLAIM FORM**

cancelled					
Customer: Delphi					
Carline:					
Model Year:					
Change went					
into effect: 7/1/2005					
Detailed Explanation: Customer has cancelled the launch of part numbers 04608533AD, 04608699AB,					
04608700AC, 04896705AA					
	·····				
ITEM# DESCRIPTION QUANTITY PRICE/UOM TOT.					
12048108 CLIP 2497 \$ 0.181 \$	451.96				
18-0021-14-15	932.30				
	,227.70				
20-0021-14-12	462.54				
	,042.46				
	822.18				
	,152.25				
	,890.00				
4661958 CONNECTOR 2951 \$ 0.256 \$	755.46				
4661960 CONNECTOR 2971 \$ 0.256 \$	760.58				
4661962 CONNECTOR 2971 \$ 0.256 \$	760.58				
4661974 WEDGE 5837 \$ 0.050 \$	291.85				
4687907 CONNECTOR 646 \$ 0.322 \$	208.01				
	,245.31				
4794125AA CONNECTOR 1461 \$ 0.414 \$	604.85				
	,100.00				
	,132.00				
M3531101 LABEL 5839 \$ 0.053 \$	309.47				
ZFB-05075-CH SOCKET ASSEMBLY 1397 \$ 0.654 \$	913.64				
	,029.59				
04608699AB-B FINISHED HARNESS 102 \$ 4.2956 \$	438.16				
04608700AC-A FINISHED HARNESS 56 \$ 2.4583 \$	137.66				
04896705AA-A FINISHED HARNESS 54 \$ 5.3556 \$	289.20				
<u> </u>	-				
\$					
	-				
S S	*				
CLAIM TOTAL: \$ 29	957 73				

A PO should be issued for the claim total amount. If needed, Sales or Customer Service can be contacted regarding this issue.

Clements Mfg. L.L.C



36199 Mound Rd. Sterling Heights, MI 48310 Phone 586-983-4270 Fax 586-983-3531

# **CLAIM FORM**

Part number(s) affected: 05087271AA

DATE:	6/8/2005	Part number(s) affected: 05087271AA				
Customer:	Delphi					
				Carline:	אומ	
			M	cariine: lodel Year:		
			IA:	ouel leal.		
Change went into effect:				·		
Detailed Explanation:	It was determined the drawing	supplied by the cu	ıstomei	r indicated t	he inco	rrect
Detailed Explanation	terminal part number 15491331	<ul> <li>The correct ter</li> </ul>	minal to	be used is	15418	441 at a
	quantity of four per harness. T	ne incorrect termi	nal was	s purchased	, but no	ow we
	have to expedite the correct ter	minal to allow for	the pro	duction.		
nnosa. 1.4 hl. a Janessa - 24a - 7 stippenintonin kanninin in 1885 i 1876 i 3			- 55			TOTAL :
· ITEM#	DESCRIPTION	QUANTITY	BOARD CONTRACTOR		\$	3,192.06
15491331	terminal	159763	<u>\$</u> \$	0.02 191.52	<u> </u>	191.52
Handling charge	6% raw value	1	<del>\$</del>	230.00	\$ \$	230.00
Expedite charge	cost to expedite correct item		Φ	230.00	\$	230.00
	counter to counter via American Airlines				<u>\$</u>	<del></del>
	American Amines				\$	
					\$	-
······································					\$	-
					\$	+
					\$	-
			······································		\$	-
		****			\$	-
					\$	-
······································					\$	-
					\$	-
					\$	-
					\$	*
		<u> </u>			\$	
		<u> </u>			\$	<del></del>
		**************************************			\$	-
					\$	-
				······	\$	
					\$ \$	
					<del>\$</del>	**************************************
					\$ \$	
					<u> </u>	
			CLA	IM TOTAL		3.613.59

A PO should be issued for the claim total amount. If needed, Sales or Customer Service can be contacted regarding this issue.

05-44481-rdd Doc 11484-3 Filed 12/17/07 Entered 12/17/07 18:10:45 Exhibit 1 to Affidavit of Harold Zaima - Copy and Supporting Documentati Pg 4 of 6 Page 1 of 1

### Delgado, Sue

From:

Nye, John

Sent:

Tuesday, May 10, 2005 12:18 PM

To:

Hill, Charlie; Miller, McGustavus; Simcox, Kurt

Cc:

Blancarte, Jaime; Clough, John; Lassila, Robert

Subject:

RE: Part number 05059132AA, Delphi PIA LX (Change view for clip 13551673)

Follow Up Flag: Follow up

Flag Status:

Red

#### Gus/Kurt;

There was a change in a view of the harness print on the last revision sent to the plant for subject part. Attached is the information on the cost of that change in fixtures.

John Nye

From: Hill, Charlie

Sent: Tuesday, May 10, 2005 12:04 PM

To: Nye, John

Cc: Blancarte, Jaime

Subject: FW: Part number 05059132AA, Delphi PIA LX (Change view for clip 13551673 )

Below are the clip fixtures that are no longer good for the LX harness 05059132AA. Total cost in USD is \$191.00. Let me know if you need anything else. Charlie.

From: Casas, Edith

Sent: Mon 5/9/2005 1:18 PM To: Blancarte, Jaime; Hill, Charlie

Cc: Ortiz, Alejandro

Subject: Part number 05059132AA, Delphi PIA LX (Change view for clip 13551673)

In the new blue print 05059132AA for clip 13551673 (Item 5) the figure of the clip was changed and Section "1-

1" (View for clip) was added.

The fixtures for this clip were ordered with the previous blue print (revision D(01)) and it cannot be used with the new blue print (revision D(03)), change clip position 90 degrees.

For the new revision the following fixtures are required:

6 fixtures for assembly boards

1 fixture for electrical board.

EDITH CASAS R.

Engineering Department

KenSa de México

Formely Clements Manufacturing de México ecasas@kensallc.com

Ph. +52(656) 681-53-41 xt 238

(656) 681-53-43

05-44481-rdd Doc 11484-3 Filed 12/17/07 Entered 12/17/07 18:10:45 Exhibit 1 to Affidavit of Harold Zaima - Copy and Supporting Documentati Pg 5 of 6 Page 1 of 1

## Delgado, Sue

From:

Lassila, Robert

Sent:

Tuesday, July 26, 2005 2:31 PM

To:

Simcox, Kurt

Subject:

FW: Terminal validation UScar21 Delphi PIA

Follow Up Flag: Follow up

Flag Status:

Red

From: Lassila, Robert

Sent: Wednesday, July 13, 2005 1:44 PM

To: Nye, John; Clough, John; Miller, McGustavus

Cc: Zaima, Hal

Subject: Terminal validation UScar21 Delphi PIA

Total UScar21 validation for Delphi is:

Environmental: \$19,280 Cross Sections: \$4,250 Total: \$23,530

04896705       Electrical Fixtures       4       204.39         Lock Block       1       153.29         Mechanical Fixtures       2       42.58         Sub Total       519.49         04608699       Tables       2       340.65         Electrical Fixtures       3       153.29         Lock Block       1       153.29         Mechanical Fixtures       4       95.38         Elevators       1       21.29         Sub Total       763.90         04608700       Tables       2       238.46         Electrical Fixtures       2       238.46         Electrical Fixtures       2       102.20         Lock Block       1       153.29         Mechanical Fixtures       4       21.29         Sub Total       637.88         04608533       Tables       2       408.78         Electrical Fixtures       5       255.49         Lock Block       1       153.29         Mechanical Fixtures       6       143.07         Elevators       3       63.87         Sub Total       1,024.50       2,945.77	PART NO.	DESCRIPTION	QUANTITY	TOTAL COST
Mechanical Fixtures 5 119.23 Elevators 2 42.58 Sub Total 519.49  04608699 Tables 2 340.65 Electrical Fixtures 3 153.29 Lock Block 1 153.29 Mechanical Fixtures 4 95.38 Elevators 1 21.29 Sub Total 763.90  04608700 Tables 2 238.46 Electrical Fixtures 2 102.20 Lock Block 1 153.29 Mechanical Fixtures 2 102.20 Lock Block 1 153.29 Mechanical Fixtures 4 122.64 Elevators 1 21.29 Sub Total 637.88  04608533 Tables 2 408.78 Electrical Fixtures 5 255.49 Lock Block 1 153.29 Mechanical Fixtures 6 143.07 Elevators 3 63.87 Sub Total 1,024.50	04896705	Electrical Fixtures	4	204.39
Elevators   2   42.58   Sub Total   519.49   O4608699   Tables   2   340.65   Electrical Fixtures   3   153.29   Lock Block   1   153.29   Mechanical Fixtures   4   95.38   Elevators   1   21.29   Sub Total   763.90   O4608700   Tables   2   238.46   Electrical Fixtures   2   102.20   Lock Block   1   153.29   Mechanical Fixtures   4   122.64   Elevators   1   21.29   Sub Total   637.88   O4608533   Tables   2   408.78   Electrical Fixtures   5   255.49   Lock Block   1   153.29   Mechanical Fixtures   5   255.49   Lock Block   1   153.29   Mechanical Fixtures   6   143.07   Elevators   3   63.87   Sub Total   1,024.50   I,024.50		Lock Block	1	153.29
Sub Total         519.49           04608699         Tables         2         340.65           Electrical Fixtures         3         153.29           Lock Block         1         153.29           Mechanical Fixtures         4         95.38           Elevators         1         21.29           Sub Total         763.90           O4608700         Tables         2         238.46           Electrical Fixtures         2         102.20           Lock Block         1         153.29           Mechanical Fixtures         4         122.64           Elevators         1         21.29           Sub Total         637.88           04608533         Tables         2         408.78           Electrical Fixtures         5         255.49           Lock Block         1         153.29           Mechanical Fixtures         6         143.07           Elevators         3         63.87           Sub Total         1,024.50		Mechanical Fixtures	5	119.23
04608699         Tables         2         340.65           Electrical Fixtures         3         153.29           Lock Block         1         153.29           Mechanical Fixtures         4         95.38           Elevators         1         21.29           Sub Total         763.90           04608700         Tables         2         238.46           Electrical Fixtures         2         102.20           Lock Block         1         153.29           Mechanical Fixtures         4         122.64           Elevators         1         21.29           Sub Total         637.88           04608533         Tables         2         408.78           Electrical Fixtures         5         255.49           Lock Block         1         153.29           Mechanical Fixtures         6         143.07           Elevators         3         63.87           Sub Total         1,024.50		Elevators	2	42.58
Electrical Fixtures   3   153.29     Lock Block   1   153.29     Mechanical Fixtures   4   95.38     Elevators   1   21.29     Sub Total   763.90     O4608700   Tables   2   238.46     Electrical Fixtures   2   102.20     Lock Block   1   153.29     Mechanical Fixtures   4   122.64     Elevators   1   21.29     Sub Total   637.88     O4608533   Tables   2   408.78     Electrical Fixtures   5   255.49     Lock Block   1   153.29     Mechanical Fixtures   6   143.07     Elevators   3   63.87     Sub Total   1,024.50     Indicate the properties of		Sub Total		519.49
Lock Block 1 153.29  Mechanical Fixtures 4 95.38  Elevators 1 21.29  Sub Total 763.90  04608700 Tables 2 238.46  Electrical Fixtures 2 102.20  Lock Block 1 153.29  Mechanical Fixtures 4 122.64  Elevators 1 21.29  Sub Total 637.88  04608533 Tables 2 408.78  Electrical Fixtures 5 255.49  Lock Block 1 153.29  Mechanical Fixtures 5 255.49  Lock Block 1 153.29  Mechanical Fixtures 6 143.07  Elevators 3 63.87  Sub Total 1,024.50	04608699	Tables	2	340.65
Mechanical Fixtures 4 95.38 Elevators 1 21.29 Sub Total 763.90  04608700 Tables 2 238.46 Electrical Fixtures 2 102.20 Lock Block 1 153.29 Mechanical Fixtures 4 122.64 Elevators 1 21.29 Sub Total 637.88  04608533 Tables 2 408.78 Electrical Fixtures 5 255.49 Lock Block 1 153.29 Mechanical Fixtures 5 255.49 Lock Block 1 153.29 Mechanical Fixtures 6 143.07 Elevators 3 63.87 Sub Total 1,024.50		Electrical Fixtures	3	153.29
Elevators 1 21.29  Sub Total 763.90  04608700 Tables 2 238.46  Electrical Fixtures 2 102.20  Lock Block 1 153.29  Mechanical Fixtures 4 122.64  Elevators 1 21.29  Sub Total 637.88  04608533 Tables 2 408.78  Electrical Fixtures 5 255.49  Lock Block 1 153.29  Mechanical Fixtures 5 255.49  Lock Block 1 153.29  Mechanical Fixtures 6 143.07  Elevators 3 63.87  Sub Total 1,024.50		Lock Block	1	153.29
Sub Total         763.90           04608700         Tables         2         238.46           Electrical Fixtures         2         102.20           Lock Block         1         153.29           Mechanical Fixtures         4         122.64           Elevators         1         21.29           Sub Total         637.88           04608533         Tables         2         408.78           Electrical Fixtures         5         255.49           Lock Block         1         153.29           Mechanical Fixtures         6         143.07           Elevators         3         63.87           Sub Total         1,024.50		Mechanical Fixtures	4	95.38
04608700         Tables         2         238.46           Electrical Fixtures         2         102.20           Lock Block         1         153.29           Mechanical Fixtures         4         122.64           Elevators         1         21.29           Sub Total         637.88           04608533         Tables         2         408.78           Electrical Fixtures         5         255.49           Lock Block         1         153.29           Mechanical Fixtures         6         143.07           Elevators         3         63.87           Sub Total         1,024.50		Elevators	1	21.29
Electrical Fixtures 2 102.20 Lock Block 1 153.29 Mechanical Fixtures 4 122.64 Elevators 1 21.29 Sub Total 637.88  04608533 Tables 2 408.78 Electrical Fixtures 5 255.49 Lock Block 1 153.29 Mechanical Fixtures 6 143.07 Elevators 3 63.87 Sub Total 1,024.50		Sub Total		763.90
Lock Block 1 153.29  Mechanical Fixtures 4 122.64  Elevators 1 21.29  Sub Total 637.88  04608533 Tables 2 408.78  Electrical Fixtures 5 255.49  Lock Block 1 153.29  Mechanical Fixtures 6 143.07  Elevators 3 63.87  Sub Total 1,024.50	04608700	Tables	2	238.46
Mechanical Fixtures 4 122.64 Elevators 1 21.29 Sub Total 637.88  04608533 Tables 2 408.78 Electrical Fixtures 5 255.49 Lock Block 1 153.29 Mechanical Fixtures 6 143.07 Elevators 3 63.87 Sub Total 1,024.50		Electrical Fixtures	2	102.20
Elevators 1 21.29  Sub Total 637.88  04608533 Tables 2 408.78  Electrical Fixtures 5 255.49  Lock Block 1 153.29  Mechanical Fixtures 6 143.07  Elevators 3 63.87  Sub Total 1,024.50		Lock Block	1	153.29
Sub Total         637.88           04608533         Tables         2         408.78           Electrical Fixtures         5         255.49           Lock Block         1         153.29           Mechanical Fixtures         6         143.07           Elevators         3         63.87           Sub Total         1,024.50		Mechanical Fixtures	4	122.64
04608533         Tables         2         408.78           Electrical Fixtures         5         255.49           Lock Block         1         153.29           Mechanical Fixtures         6         143.07           Elevators         3         63.87           Sub Total         1,024.50		Elevators	1	21.29
Electrical Fixtures 5 255.49 Lock Block 1 153.29 Mechanical Fixtures 6 143.07 Elevators 3 63.87 Sub Total 1,024.50		Sub Total		637.88
Lock Block       1       153.29         Mechanical Fixtures       6       143.07         Elevators       3       63.87         Sub Total       1,024.50	04608533	Tables	2	408.78
Mechanical Fixtures       6       143.07         Elevators       3       63.87         Sub Total       1,024.50		Electrical Fixtures	5	255.49
Elevators 3 63.87 <b>Sub Total 1,024.50</b>		Lock Block		153.29
Sub Total 1,024.50		Mechanical Fixtures		
		Elevators	3	
Grand Total 2,945.77		Sub Total		1,024.50
		Grand Total		2,945.77